

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,092,499 B2
APPLICATION NO. : 10/628405
DATED : August 15, 2006
INVENTOR(S) : Hitoshi Saito et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 36, "change." should read --changes--.

COLUMN 8:

Line 32, "to" (first occurrence) should be deleted; and
Line 65, "changes" should read --changing--.

COLUMN 9:

Line 28, "if" should be deleted.

COLUMN 10:

Line 51, "reaches directly" should read --directly reaches--.

COLUMN 14:

Line 27, "operation of the" (second occurrence) should be deleted; and
Line 52, "operation of the" (second occurrence) should be deleted.

COLUMN 16:

Line 6, "alter" should read --later--.

COLUMN 18:

Line 31, "why" should read --why it is--; and
Line 35, "issured" should read --issued--.

COLUMN 19:

Line 22, "bride" should read --bridge--; and
Line 31, "OF/ON," should read --OFF/ON,--.

COLUMN 22:

Line 56, "eliminating" should read --eliminate--.

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,092,499 B2
APPLICATION NO. : 10/628405
DATED : August 15, 2006
INVENTOR(S) : Hitoshi Saito et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 23, "here" should read --where--.

COLUMN 24:

Claim 6, Line 7, "time" should read --of time--;

Claim 13, Line 40, "disconnecting" (both occurrences) should read
--connecting/disconnecting--;

Claim 13, Line 41, "from a line during dialing; and" should read --to/from a
line--;

Claim 13, Line 43, "current by connecting the" should read --current; and--;

Claim 13, Line 44, "handset to the line in an inter-digit time of dialing." should
read --control means for causing said line connecting/disconnecting
means to disconnect the handset from the line in the process of
transmitting a dial digit signal, and for, during the time period between
digits of the dial signal, causing said line connecting/disconnecting
means to connect the handset to the line and then causing said hook
state detecting means to detect a hook state of the handset.--;

Claim 14, Line 48, "the" (first occurrence) should read --an-- and "time" should
read --time of dialing--;

Line 53, "the" (third occurrence) should read --an--;

Line 54, "time" should read --time of dialing--;

Line 63, "means" (second occurrence) should read --a means--;

Line 64, "the" (second occurrence) should read --an-- and "time" should read
--time of dialing--; and

Line 66, "receiving" should read --received--.

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,092,499 B2
APPLICATION NO. : 10/628405
DATED : August 15, 2006
INVENTOR(S) : Hitoshi Saito et al.

Page 3 of 3


It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 26:

Line 62, "means" (second occurrence) should read --a means--.

Signed and Sealed this

Twenty-second Day of May, 2007

A handwritten signature in black ink, reading "Jon W. Dudas". The signature is stylized with a large, looping initial "J" and a cursive "Dudas".

JON W. DUDAS
Director of the United States Patent and Trademark Office